

ORIGINAL

Rick Pierce
Katherine Resort Water Compar
3210 Katherine Drive
Bullhead City, AZ 86429



0000014446

50

November 23, 2004

Director
Utilities Division
Arizona Corporation Commission
1200 West Washington Street
Phoenix, AZ 85007

Arizona Corporation Commission
DOCKETED

NOV 26 2004

DOCKETED BY	<i>CR</i>
-------------	-----------

Report to Director Concerning Arsenic Levels

Dear Director:

As ordered by Decision NO. 67066, Docket No. W-01751A-03-0036, Findings of Fact No. 27 (I), this report addresses arsenic levels and the requirement to reduce the levels to a concentration below 10 ppb.

Please find enclosed a copy of the report filed by Mohave Environmental Laboratory On Oct. 21, 2004. The arsenic level is less than 5 ppb.

We do not plan any changes to our water system.

Sincerely,

Rick Pierce
On Site Manager
Katherine Resort Water Company System ID # 08-018
928-754-3226

RECEIVED

2004 NOV 26 1 A 10:51

AZ CORP COMMISSION
DOCUMENT CONTROL



Customer Name: Katherine Mine Water
Lab ID: 10284
Sample Type: Drinking Water
Sampled By: J. Wileman

Date Received: 10/18/04 14:05
Date Reported: 10/21/04

Analytical Results

Parameter	Method	Result	Units	Detect Limit	Date	Analyst
-----------	--------	--------	-------	--------------	------	---------

10284-01

Sample Date: 10/18/04 13:40

POE 001

08-018

METALS, TOTAL

Arsenic, Total	EPA 200.9	<0.005	mg/L	0.005	10/20/2004	CM
Turbidity	SM2130	<1.0	NTU's	1	10/19/2004	CM
Nitrogen, Nitrate	EPA 300.0	3.14	mg/L	0.1	10/18/2004	JP

Received in lab @ 25 degrees C.

Christina Montoya
Lab Manager

Arizona Department of Environmental Quality
Water Quality Compliance Assurance Unit
1110 W. Washington Street, 5415B-1
Phoenix, AZ 85007

Drinking Water Compliance Status Report

Public Water System Name: Katherine Resorts Landing

Public Water System ID #: 08-018

Public Water System Type: ☒ CO ☐ Non-transient Non-community ☐ Transient Non-community

Overall Compliance Status: ☒ No Major Deficiencies ☐ Major Deficiencies

Monitoring and Reporting Status: ☒ No Major Deficiencies ☐ Major Deficiencies
Comments:

Operation and Maintenance Status: ☒ No Major Deficiencies ☐ Major Deficiencies
Comments:

Major unresolved/ongoing operation and maintenance deficiencies:

- | | |
|---|---|
| <input type="checkbox"/> unable to maintain 20psi | <input type="checkbox"/> inadequate storage |
| <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| <input type="checkbox"/> treatment deficiencies | <input type="checkbox"/> approval of construction |
| <input type="checkbox"/> certified operator | <input type="checkbox"/> other |

Date of last inspection / sanitary survey: 10-17-96

Administrative Orders:

Is an ADEQ administrative order in effect? ☐ Yes ☒ No

Comments:

System information:

Number of Points of Entry 1 **Number of Sources** 1 **Population Served** 78

Service Connections 42 **Initial Monitoring Year** 42 **Initial MAP Year** 2001

Evaluation completed by: Jim Puckett

Phone: 602-771-4649 **Date:** 11-23-04

Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.